

## Office of the Secretary, HUD

## § 35.110

1965. The property is financed with HUD multifamily mortgage insurance. This building is covered by subpart G of this part (see § 35.625—Multifamily mortgage insurance for properties constructed after 1959), which is at protectiveness level 5 in the table set forth in paragraph (c) of this section. In the same building, however, 50 of the 100 dwelling units are receiving project-based assistance, and the average annual assistance per assisted unit is \$5,500. Those 50 units, and common areas servicing those units, are covered by the requirements of subpart H of this part (see § 35.715—Project-based assistance for multifamily properties receiving more than \$5,000 per unit), which are at protectiveness level 3.

Therefore, because level 3 is a higher level of protectiveness than level 5, the units receiving project-based assistance, and common areas servicing those units, must comply at level 3, while the rest of the building can be operated at level 5. The owner may choose to operate the entire building at level 3 for simplicity.

(c) *Table One.* The following table lists the subparts and sections of this part applying to HUD programs in order from most protective to least protective hazard reduction requirements. The summary of hazard reduction requirements in this table is not complete. Readers must refer to relevant subpart for complete requirements.

Level of protection	Subpart, section, and type of assistance	Hazard reduction requirements
1 .....	Subpart L, Public housing. Subpart G, § 35.630, Multifamily mortgage insurance for conversions and major rehabilitations.	Full abatement of lead-based paint.
2 .....	Subpart J, § 35.930(d), Properties receiving more than \$25,000 per unit in rehabilitation assistance.	Abatement of lead-based paint hazards.
3 .....	Subpart G, § 35.620, Multifamily mortgage insurance for properties constructed before 1960, other than conversions and major rehabilitations. Subpart H, § 35.715, Project-based assistance for multifamily properties receiving more than \$5,000 per unit. Subpart I, HUD-owned multifamily property. Subpart J, § 35.930(c), Properties receiving more than \$5,000 and up to \$25,000 per unit in rehabilitation assistance.	Interim controls.
4 .....	Subpart F, HUD-owned single family properties. Subpart H, § 35.720, Project-based rental assistance for multifamily properties receiving up to \$5,000 per unit and single family properties. Subpart K, Acquisition, leasing, support services, or operation. Subpart M, Tenant-based rental assistance.	Paint stabilization.
5 .....	Subpart G, § 35.625, Multifamily mortgage insurance for properties constructed after 1959.	Ongoing lead-based paint maintenance.
6 .....	Subpart J, § 35.930(b), Properties receiving up to and including \$5,000 in rehabilitation assistance.	Safe work practices during rehabilitation.

### § 35.105 Effective dates.

The effective date for subparts B through R of this part is September 15, 2000, except that the effective date for prohibited methods of paint removal, described in § 35.140, is November 15, 1999. Subparts F through M of this part provide further information on the application of the effective date to specific programs. Before September 15, 2000, a designated party has the option of following the procedures in subparts B through R of this part, or complying with current HUD lead-based paint regulations.

### § 35.106 Information collection requirements.

The information collection requirements contained in this part have been approved by the Office of Management and Budget (OMB) in accordance with the requirements of the Paperwork Reduction Act of 1995 (44 U.S.C. 2501–3520), and have been assigned OMB control number 2539–0009. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the collection displays a valid control number.

### § 35.110 Definitions.

*Abatement* means any set of measures designed to permanently eliminate